

PDL Notice:

## Platelet Function Screen

### Temporarily to be Sent Out

July 10, 2020

#### Issue:

Due to an instrument malfunction, Pacific Diagnostic Laboratories (PDL) is **temporarily routing the following test to an alternate community laboratory:**

#### **Platelet Function Screen LAB9419 (PFA)**

**STAT:** Due to the 4-hour stability of this test, it is essential that it be treated as a STAT. If your office collects for this test call for a **STAT pick-up** in advance of collecting to allow for coordination of the collection, transport, testing within this limited timeframe.

#### Expected Resolution:

PDL anticipates that the Platelet Function Screen will be performed in-house again in approximately two weeks.

#### If you have additional questions:

Please contact us at PDL Client Services at (805) 879-8100

Please accept our apologies for this inconvenience.

Stewart W. Comer, MD FCAP  
Medical Director Pacific Diagnostic Laboratories